

PRODUCT MATERIALS

Standard Office Product Lines

Morency Rests:

- Plywood Base Material
- 1/2" Foam Padding
- Black Nylon-Polyester Knit Fabric
- Non-Slip Rubber Backing
- Zinc plated steel tee nuts
- Durable, Easy to Clean

Mounting Clamps:

- Solid wood spacer
- Mild steel plate, painted gloss black
- Hardened steel socket head cap screws

Vinyl Industrial/Medical Product Lines

Morency Rests:

- Plywood Base Material
- 1/2" Foam Padding
- Black Vinyl Covering
- Non-Slip Rubber Backing
- Zinc plated steel tee nuts
- Durable, Antimicrobial, Disinfectable

Mounting Clamps:

- Polyethylene spacer
- Mild steel plate, painted gloss black
- Hardened steel socket head cap screws

ESD Applications

Morency Rests:

- Plywood Material
- 1/2" Foam Padding
- Black High Grade ESD Vinyl Covering
Surface Resistivity $<1.0 \times 10^6$ ohms/sq. using #819 Beckman Megohmmeter and a 500 volt charge
- Non-Slip Rubber Backing
- Zinc plated steel tee nuts
- Grounding screw connection

Mounting Clamps:

- Polyethylene spacer
- Mild steel plate, painted gloss black
- Hardened steel socket head cap screws

Note: Customer is responsible for properly providing a resistive grounding cable meeting their own specific grounding requirements.

Clean Room Applications

Morency Rests:

- Polyethylene Base Material
- 1/2" Foam Padding
- Black High Grade ESD Vinyl Covering
Surface Resistivity $<1.0 \times 10^6$ ohms/sq. using #819 Beckman Megohmmeter and a 500 volt charge
- Black ESD Vinyl Backing
- Stainless steel grounding screw connection

Mounting Clamps:

- Polyethylene spacers
- Stainless steel plates
- Stainless steel socket head cap screws

Note: Customer is responsible for properly providing a resistive grounding cable meeting their own specific grounding requirements.

Notes:

Our products were designed and fabricated using materials suitable for the above environments. We do not however package these products in a sterile environment so the customer must clean and prepare them for entry into the work area. Cleaning with warm water and a soft cloth and vacuuming any residues is highly recommended. The customer is responsible for verifying that these products will meet their individual requirements.